COMPONENT CODE 47

PARTS & SERVICE NEWS

REF NO. | AA03059

DATE April 3, 2003

Page 1 of 2

SUBJECT: REAR AXLE WELD CRACKS AT SUSPENSION MOUNTS & REINFORCEMENT PLATE

PURPOSE: To inform the field of repair instructions for weld cracks found in upper area of suspension mounts and around the bottom of axle housing access hele reinforcement plate.

APPLICATION: Komatsu Electric Drive Dump Trucks: 930E: 32604 - 32816, A30019, A30026 and up; 930E-2: A30012, A30098, A30100, A30121 and up

FAILURE CODE: 4765HB

DESCRIPTION:

Some trucks in the field may experience weld cracks in the upper cre. of suspension mounts and around the bottom of axle housing access hole reinforcement plate. Caleful y inspect each area for cracking at the welded joints. If cracks are found, follow the procedure out ined below to properly repair the cracks.

REPAIR PROCEDURE:

- 1. Repair any weld cracks at the suspension mounts and reinforcement plates. Follow the guidelines that are outlined in Parts & Service News "FIELD WELDING FOR ASSEMBLY OR REPAIR" (AA00046B).
- 2. Suspension Mounts Add 25 minufallet weld around upper part of suspension mount as shown in Figure 1, Section A-A. The vere must have a smooth profile and the toe must have a good transition to the parent material before peening is performed. Grinding the weld face and toe area is permitted to correct unacceptable conditions.
- 3. Visually inspect the well before peening.
- 4. Peen the type of the 25 mm fillet weld per Parts & Service News (AA00046B, Annex B 1.0).
- 5. Visual ispection / acceptance is to be completed after peening per Parts & Service News (AA00040B, Annex B 1.0).
- 6. **Reinforcement Plates** Grind the toe of the weld in the area shown in Figure 1, Section B-B per Parts & Service News (AA00046B, Annex B 2.0).
- 7. Visual inspection / acceptance is to be completed after grinding per Parts & Service News (AA00046B, Annex B 2.0).



