PARTS & SERVICE NEWS

Ref.no.	AH04007
Date.	05.07.2004

Page 1 of 3

Subject: Modification procedure of muffler bracket on WA470-5H and WA480-5H.

Purpose: To introduce modification procedure to repair cracks on the muffler bracket for the

SAA6D125 engines being used for WA470-5H and WA480-5H wheel loaders

Application: WA470-5H S/N: H50051 up to H50811

WA480-5H S/N: H60051 up to H60351

Failure code: A1V0HA

Description:

1. Introduction


When cracks occur on the muffler bracket for the SAA6D125 engines being used for the WA470-5H and WA480-5H wheel loaders, repair the cracks following the modification procedure described in this Service News.

2. List of parts

Part No.	Part Name	Purpose of purt	Q'ty	Remarks
6156-11-5611 (6156-11-5610)	Bracket (Bracket	Remacement	1 (1)	Part "①" in the "Modification procedure"
01010-E1055 (01010-E1050)	Bolt (Bolt)	Replacement	2 (2)	Part "②" in the "Modification procedure"
6631-11-5630	Spacer		2	Part "3" in the "Modification procedure"
6215-11-5740	Nu.		2	Part "④" in the "Modification procedure"
01643-31032	Washer		2	Part "S" in the "Modification procedure"
6156- (-5230	Band		1	Part "©" in the "Modification procedure"


AH04007 Page 2 of 3

3. Details of modification



Details of the modification of the brocket

- (1) The muffler sitting section (9 mm thick plate \rightarrow 25 mm machined block)
- (2) The plate thickness has been changed and, moreover, the plate length along the muffler sitting section has been extended.



AH04007 Page 3 of 3

4. Modification procedure

<<Removal procedure>>

- (1) Loosen the nut @ remove the band @.
- (2) Loosen the bolt ② and remove the bracket ①.

<<Installation procedure>>

(1) Fasten the new bracket ① by the spacers ③ and the new bolts ②. (Bolt tightening torque: $58.8 - 73.5 \text{ Nm} \{6.0 - 7.5 \text{ kgm}\}$)

(2) Setting the band ©, fasten it by the nuts ④ and washers ⑤. (Nut tightening torque: 9.8 – 14.7 Nm {1.0 – 1.5 kgm})




Fig. 3