PARTS & SERVICE REF NO. AT01234 DATE Jan. 9, 2002 Page 1 of 4

SUBJECT: INTRODUCTION OF IMPROVED DOWEL PIN ON S(A, AA)6D140 ENGINE FOR SEPARATE MARKETING

- **PURPOSE:** To introduce improved dowel pin effective to prevent occurrence of cracks in the cylinder block of the independently marketed S(A, AA)6D140 series engines
- **APPLICATION:** Refer to page 4
- FAILURE CODE: A200HA

DESCRIPTION:



1. Introduction

There is a possibility of occurrence of cracks in the cylinder block of the independently marketed S(A, AA)6D140 series engines depending on the outfitting conditions. This Service News will introduce a new dowel pin with an inproved shape to prevent occurrence of the aforesaid cracks in the cylinder block


It is recommended to use this new dowel pin t the time of conducting overhauling of these engines or at a similar opportunity.

2. List of parts

| Part No. | Par ⁺ Na ne | Q'ty | Remarks |
|---|------------------------------|-------------------------------------|--|
| $\begin{array}{c} 6211 - 22 - 1102 \\ (6211 - 22 - 1101) \end{array}$ | Plock ass'y (Block ass'y) | 1 (1) | The dowel pin indicated below only has been changed. (Type-2 cylinder block ass'y) |
| 6211-21-(10) (6211-21-110?) | Block ass'y (Block ass'y) | 1 (1) | The dowel pin indicated below only has been changed. (Type-1 cylinder block ass'y) |
| 0212-22-1110 (04020-00514) | Pin (Pin) | $\begin{array}{c}2\\(2)\end{array}$ | |


2. Contents of the modification

The shape of the dowel pins being used for installation of the #7 main cap has been changed to alleviate the stress being occurred in the cylinder block.




- 3. Modification procedures
 - (1) Remove and reinstall the main cap referring to the Shop Manual for the $$\phi140 series engines.
 - <Note> Since the pins are being inserted as shown in this Service News, do not try to hammer the main cap forcibly in the longitudinal direction when removing and reinstalling the cap.

(If it is hammerred forcibly in the longitudinal direction, the main cap or the cylinder block may be damaged.)



(2) Adjust the projection of the new dowel pins from the cylinder block relevant to this modification to the following distance (8 1 121).



(Check table for the serial numbers of the engines which change has been made to implement the modification introduced in this Service News.

| | Applicable serial Nos. | | Imple- menta- | | A 1' 11 | Applicable serial Nos. | | Imple- menta- | |
|----|-----------------------------|-------------------------------|---|--------------------------------|---------|-----------------------------|-------------------------------|---|--------------------------------|
| | Applicable engine models | Already shipped engines | Already modi- fied factory ship- ment engines | tion start- ing from: | No. | Applicable engine models | Already shipped engines | Already modi- fied factory ship- ment engines | tion start- ing from: |
| 1 | EG300-5 | |] | | 31 | SA6D140A-G3-1 | | | |
| 2 | EG300B-5 | | | | 32 | SA6D140A-GA-1 | | | |
| 3 | EG300BS-5 | | - | | 33 | SA6D140A-GB-1 | | | |
| 4 | EG300-L-5 | | | | 34 | SA6D140A-GD-1 | | | |
| 5 | EB350A-L-1 | | Next production | | 35 | SA6D140A-GH-1 | | | |
| 6 | EG350B-L-1 | | and after | | 36 | SA6D140A-GJ-1 | | | |
| 7 | EG400-2 | | | | 37 | SA6D140A-GN-1 | | Next production | |
| 8 | EG400B-2 | | | | 38 | SA6D140A-GT-1 | | and after | |
| 9 | EG400B-L-2 | | | | 39 | SA6D140A-P-1 | | | |
| 10 | EG400BS-2 | | J | | 40 | SA6D140A- ^v 1-1 | | | |
| 11 | J6D140E-G1-2 | - 70062 | 70063 - | Oct.16, '01 | 41 | SA6D14/ль 1 | | | |
| 12 | J6D140E-GD-2 | |] | | 42 | SA6D1401-A1-1 | | | |
| 13 | J6D140E-GE-2 | | | | 43 | SAC 214 B-G1-1 | | J | |
| 14 | J6D140E-KC-2 | | | | 44 | SP 3D1 10B-G2-1 | -29675 | 29676 - | Oct. 9, '01 |
| 15 | J6D140E-W2-2 | | | | 5 | 140B-G3-1 | | | |
| 16 | S6D140-1 | | | | 46 | SA6D140B-GA-1 | | | |
| 17 | S6D140-G1-1 | | - | | 27 | SA6D140B-GN-1 | | | |
| 18 | S6D140-G2-1 | | | $\overline{\mathbf{N}}$ | 48 | SA6D140-C2-1 | | Next | |
| 19 | S6D140-G3-1 | | Next | | 49 | SA6D140-P-1 | | production and after | |
| 20 | S6D140-GD-1 | | and any | | 50 | SA6D140-W1-1 | | | |
| 21 | S6D140-GH-1 | _ | | | 51 | SAA6D140-G1-1 | | J | |
| 22 | S6D140-GN-1 | | | | 52 | SAA6D140-G3-1 | -29682 | 29683 - | Oct. 5, '01 |
| 23 | S6D140-GT-1 | | | | 53 | T6D140E-W2-2 | | Next | |
| 24 | S6D140-P-1 | • | | | | | | production and after | |
| 25 | SA6D140-PGA-1 | | | | 54 | | | | |
| 26 | SA6D140A-1 | | | | 55 | | | | |
| 27 | SA6D140-A1.1 | | J | | 56 | | | | |
| 28 | SA6D140 42-1 | - 29673 | 29674 - | Oct. 4, '01 | 57 | | | | |
| 29 | SA671.0.1-61-1 | | Next | | 58 | | | | |
| | | | production and after | | 59 | | | | |
| 30 | SA6D140A-G2-1 | - 29674 | 29675 - | Oct. 5, '01 | 60 | | | | |