AT04090

## PARTS & SERVICE

REF NO.	AT04090			
DATE	May 21, 2004			
(C)	Page 1 of 3			

REPAIR PROCEDURE FOR EXHAUST MANIFOLD GASKET FOR SUBJECT:

SA12V140 ENGINES

**PURPOSE:** To introduce modification procedure to repair the breakage failure of

the exhaust manifold gasket for the SA12V140 engines

APPLICATION: Refer to page 3

FAILURE CODE: A1PDFF

## **DESCRIPTION:**

1. Introduction

- When the exhaust manifold gasket becomes broken by thermal expansion or contraction of the exhaust manifold for the SA12V140 engines, resulting in gas leakage failure, make the modification introduced in this Service News to repair the failure.
- When making reassembly after overhauling, in the improved gasket following the modification procedure described in this Service News.

## 2. List of parts

Part No.	Part Name	Purpose of part	Q'ty	Remarks
6218-11-5880 (6210-11-5881)	Gasket (Gasket)	Peplacement	12 (12)	
6212-15-5831	Gasket		2	Consumable parts (For the mounting surface of
02895-77075	O-Ving		8	the turbocharger) Consumable parts (For the crossover connector section of the turbo- charger)
6151-51-8167	Gasket		2	Consumable parts (For the oil inlet port of the
6151-19-8151	Gasket		2	turbocharger) Consumable parts (For the oil inlet port of the
0 <mark>164-</mark> 32-8241	Gasket		4	turbocharger) Consumable parts (For the water inlet/outlet port of the turbo- charger)
07003-01419	Gasket		6	Consumable parts (For the water inlet/outlet port of the turbo-
6211-11-5890	Gasket		2	charger) For the mounting section of the muffler (On D475 and WA800 Series machines only)

- 3. Details of the modification
  - (1) Molybdenum disulfide coating is being applied to the exhaust manifold gasket on the contact surface side to the exhaust manifold.
     (Even if the exhaust manifold moves by thermal deformation, the gasket will slips to avoid deformation. (To suppress the occurring stress)
  - (2) The structure of the gasket has been changed from 3 layer structure to 5 layer structure to equalize the surface pressure of the gasket, and also, to suppress relative deformation.




Fig. 1

4. Disassembly and reassembly Carry out this modification following the instructions given in the Shop Manual.

(Check table for the serial numbers of the machines applicable to the design change per this Service News)

(Part No. change:  $6210-11-5881 \rightarrow 6218-11-5880$ )

S		Serial No.	Serial No. of the engine		Serial No.	Modifica-	
No.	Applicable machine model	Engines in the field	Engines shipped with the modification completed	Modifica- tion starting from	Machines in the field	Machines shipped with the modofication completed	tion starting from
1	HD785-3		From the next shipment and up				
2	HD785-5	Up to 13614	13620 and up	2/24	Up to 4477	4478 and up	4/3
3	HD985-3		From the next shipment and up				
4	HD985-5		From the next shipment and up			<u> </u>	
5	HD785-2*	Up to 13603	From the next shipment and up			O	
6	HD785-JK-5	Up to 13466	From the next shipment		Up to J19642	J10043 and up	
7	D475A-2		From the next shipment	(			
8	D475A-3		From the next shipment				
9	D475A-5	Up to 13580	13616	2/23	Up to 20021	20022 and up	
10	HV700-2		From the next shipment and to				
11	WA800-1		From the yext ship ner and up				
12	WA800-2	•	frein the next applent and up				
13	WA800-3	Up to 136. 7	13638	3/11	Up to 50043 Up to 51003	50044 and up 51004 and up	
14	WA900-1		From the next shipment and up				
15	WA900-3	Up to 13638	13639	3/15	Up to 50036	50037 and up	
16	WD. 00-2		From the next shipment and up				