COMPONENT CODE A6

PARTS & SERVICE NEWS

REF NO. AT04159

DATE Sept. 30, 2004

Page 1 of 3

SUBJECT: REPAIR PROCEDURE OF OIL LEAKAGE FROM OIL COOLER FOR SAA6D114E-2 ENGINE

- **PURPOSE:** To inform field personnel
- APPLICATION: 6D114E-2 Engine S/N 26801378 thru 26803519 CD110R-2 Crawler Carrier S/N 1501 thru 1521 GD655-3A Motor Grader S/N 11001 thru11029 GD6553Y Motor Grader S/N 4001 thru 4116 GD675-3C Motor Grader S/N 51001 thru 51011 GD675-3Y Motor Grader S/N 11001 thru 11017 PC300-7 Hydraulic Excavator S/N 40001 thru 41405 PC300LC-7 Hydraulic Excavator S/N 40009 thru 41405 PC350LC-7 Hydraulic Excavator S/N 20001 thru 20201 PC350LC-7 Hydraulic Excavator S/N 20001 thru 20201 WA380-5 Wheel Loader S/N 60001 thru 61/34 WA400-5 Wheel Loader S/N 70001 thru 70022

FAILURE CODE: A620FF

DESCRIPTION:


1. Introduction

There is a rare possibility that the oil cooler cores for the SAA6D114E-2 engines have cracks and the engine oil may mix into the cooling water in the radiator. When the mixture occurs, repair the failure following the mdoification procedure described in this service news.

2. List of parts


Part No.	Port Name	Purpose of part	Q'ty	Remarks
6743-61-2210 (6742-01-245.)	Element	Replacement	1 (1)	Part No. 1
6743-51-4430	Gasket	Replacement	1	Part No. 2 Spare part
6742-01-1080	Gasket	Replacement	1	Part No. 3 Spare part





1. Details of the modification


The structure of the oil cooler element has been modified as shown in the figure below to improve the rigidity against vibrations.



Service News

AT04159

- 3) Replace the oil cooler element <1> (6742-01-2450) with the improved oil cooler element (6743-61-2210).
- 4) Replace the gasket <2> (6743-51-4430) and gasket <3> (6742-01-1080) with new parts.



- 5) Tighten the oil to ler over mounting bolts in the tightening order the vn in the drawing indicated on the RH side at the tightening torque of 24 ± 4 Nm.
- 6) Refill the raciator with cooling water and carry out a warrning up operation of the engine. After that, check that oil leakage and water leakage are not uccurring from various sections.

