

# PARTS & SERVICE NEWS

REF NO. AT04197

DATE Aug. 30, 2004

(C)

Page 1 of 4

**SUBJECT:** CHANGE OF GREASING POINTS FOR DRIVE SHAFTS

**PURPOSE:** To inform Field Personnel

**APPLICATION:** WA1200-3 Wheel Loader, S/N 50001 thru 50019  
WA800-3 Wheel Loader, S/N 50001 thru 50041  
WA900-3 Wheel Loader, S/N 50001 thru 50033  
WD900-3 Wheel Dozer, S/N 50001 thru 50011

**FAILURE CODE:** 202CNY

**DESCRIPTION:**

1. Introduction:

This **Parts & Service News** will introduce the change of the greasing points for the drive shaft since greasing to the slide spline section has become unnecessary after the change of the manufacture of the drive shafts.

2. List of Parts:

Part No.	Part Name	Qty.	Remarks
427-93-21211 (427-93-21210)	Plate (Plate)	1 (1)	Decal in English
427-93-21481 (427-93-21480)	Plate (Plate)	1 (1)	Decal in Japanese
427-93-2111 (427-93-2110)	Plate (Plate)	1 (1)	Decal in French
427-V00-2111 (427-V00-2110)	Plate (Plate)	1 (1)	Decal in Spanish
427-V06-2211 427-V06-2210	Plate (Plate)	1 (1)	Decal in Russian
427-V07-2111 (427-V07-2110)	Plate (Plate)	1 (1)	Decal in German
427-V08-2161 427-V08-2160)	Plate (Plate)	1 (1)	Decal in Turkish
42C-93-11163 (42C-93-11162)	Plate (Plate)	1 (1)	Decal in English
42C-V00-1131 (42C-V00-1130)	Plate (Plate)	1 (1)	Decal in Spanish

<b>Part No.</b>	<b>Part Name</b>	<b>Qty.</b>	<b>Remarks</b>
42C-93-11172 (42C-93-11171)	Plate (Plate)	1 (1)	Decal in Japanese
41F-93-11211 (41F-93-11210)	Plate (Plate)	1 (1)	Decal in English
41F-V00-1111 (41F-V00-1110)	Plate (Plate)	1 (1)	Decal in Spanish


<https://hespareparts.com/>

## 1. Details of the change of the grease fitting

### 1-1. Spider section (2 places)

1) The position of the grease fitting has been changed as follows.

#### Before the change



#### After the change




Fig. 1

2) Grease at the interval indicated in the Operation and Maintenance Manual.

Center drive shaft	Every 500 H
Front drive shaft	Every 1,000 H
Rear drive shaft	Every 1,000 H

### 1-2. Center spline section

The grease fitting indicated in Fig. 1 has been cancelled.

#### **IMPORTANT**

Greasing to the center spline section of the drive shaft has become unnecessary. Do not grease this section by reworking to plug the greasing port. Do not grease the spline section by removing the plug since it may cause breakage failure of the spline seal.

## 2. Revision of the oil chart

After the change of the greasing points for the front, center and rear drive shafts, the oil chart has been revised. When changing the oil chart, order the proper oil chart corresponding to the machine model and the language to use.

Applicable machine model	Applicable Serial No.	Language	Current Part No.		New Part No.
WA800-3	#51003 - (Japanese market)	English	427-93-21210	→	427-93-21211
		Japanese	427-93-21480	→	427-93-21481
	#50042 - (Overseas markets)	French	427-933-2110	→	427-933-2111
		Spanish	427-V00-2110	→	427-V00-2111
		Russian	427-V06-2210	→	427-V06-2211
WA900-3	#51002 - (Japanese market)	German	427-V07-2110	→	427-V07-2111
		Turkish	427-V08-2160	→	427-V08-2161
	#50034 - (Overseas markets)				
WA800L-3	#52001 -				
WA900L-3	#52001 -				

Applicable machine model	Applicable Serial No.	Language	Current Part No.		New Part No.
WA1200-3	#50020 -	English	42C-93-11162	→	42C-93-11163
		Spanish	42C-V00-1130	→	42C-V00-1131
		Japanese	42C-93-11171	→	42C-93-11172

Applicable machine model	Applicable Serial No.	Language	Current Part No.		New Part No.
WD900-3	#50012 -	English	41F-93-11210	→	41F-93-11211
		Spanish	41F-V00-1110	→	41F-V00-1111