**COMPONENT CODE** 44

## PARTS & SERVICE NEWS

**REF NO.** AT04421

5.00

DATE JANUARY 20, 2005

Page 1 of 5

**SUBJECT:** MODIFICATION PROCEDURE TO REPAIR THE RETURNING TROUBLE OF THE WORK EQUIPMENT CONTROL LEVER

**PURPOSE:** To inform field service Personnel

APPLICATION: GD555-3A: 10001-11064 GD555-3C: 50001-51045 GD655-3: 1001-4117 GD655-3A: 10001-11034 GD655-3C: 50001-51101 GD655-3Y: 4001-4117 GD675-3A: 10001-11017 GD675-3C: 50001-51011

FAILURE CODE: 4491MX

## **DESCRIPTION:**

## Introduction

Work equipment levers on the GD655-3 do not return to the neutral position even when the operator releases his hand from the work equipment lever, c.m. out the modification introduced in this parts and service news.

## **List of Parts**

Part No.	F	ht Name	Purpose of Part	Q'ty	Remarks
23B-43-35513 (23B-43-35, 12)		Rod (Rod)	Replacement	8 (8)	The quantities of the using parts differ depending on the installation condition of the attachment.









