	COMPON	ENT CODE 87
PARTS & SERVICE	REF NO.	AT97252
NEWS	DATE	Nov. 17, 1997
	(C)	Page 1 of 4

- SUBJECT: IMPROVED FUSE BROKEN OF AIR CONDITIONER BLOWER MOTOR ON DUMP TRUCK
- **PURPOSE:** To introduce modification procedures to prevent fusion of the fuse for the blower motor of the air conditioner on dump trucks of the models listed below.
- APPLICATION: HD325-6 Dump Trucks HD405-6 Dump Trucks HD465-5 Dump Trucks HD605-5 Dump Trucks HD785-3 Dump Trucks HD985-3 Dump Trucks

Refer to Page 2.

FAILURE CODE: 8716

DESCRIPTION:

1. Introduction

With dump trucks of the models listed above, when the power switch for the air conditioner is turned on, excessive current flows instantar early o melt the fuse in the power circuit for the blower motor for the air conditioner. To provent this failure, make the modification outlined in this Service News.

2. List of parts

Part No.	Part Name	Purpose of part	Q'ty	Remarks
08041-02000 (283-06-16190)	Гизе '20A) (Fu. 2 (10A))	Replacement	1 (1)	Use it for some other purpose.
561-93-61352 (561-93-61352)	Plate (Plate)	Reworked	1 (1)	




	Serial numbers of applicable vehicles		
Vehicle models	Already shipped vehicles	Vehicles being shipped newly from the factory (This modification has already been made.)	
HD325-6	#5576 - #5641 #5643 - #5649 #5656, #5657	#5642 #5650 – #5655 #5658 –	
HD405-6	#1009 - #1023, #1027 #1029 - # 1039 #1041 - #1043	#1024 – #1026, #1028 #1040, #1044 –	
HD465-5	#4461 - #4584 #4586 - #4595 #4599 - #4602 #4605 - #4617 (The fuse has already been replaced with the improved one with #4608 - #4617 and change the label only.)	#4585, #4596 - #459 <i>3</i> #4603 - #4604 #4618 -	
HD605-5	#1007, #1009 – #1012	#1000 #1010, #1013 -	
HD785-3	#2459 – #2517 #2519 – #2565	#1513 , # 2566 –	
HD985-3	#1013 – #1015, #1017	#1012, #1016, #1018 -	

hilps. These

Applicable vehicles for this modification to prevent fusion of the fuse for the blower motor of the air conditioner on dump trucks HD325 thru HD985


- 3. Replacing the fuse for the blower motor of the air conditioner and changing the nameplate
 - 1) Replace the fuse (Fuse No. 23 in the fuse box III) for the blower motor of the air conditioner ($10A \rightarrow 20A (08041-02000)$).



Fuse Box III

No.	Fuse capacities	Circuit names
23	10A	AISS motor (HD785-3 & HD985-3)
22	20A	Wiper motor, washer motor
▶23	$10A \rightarrow 20A$	Blower motor for the air conditioner
24	10A	Air compressor
25	10A	Spare
26	20A	APS power (HD465-5 & HD605-5)

2) Open the cover located at rear of the operato.'s seat and correct the fuse capacity for the blower motor for the air conditioner on the fuse layout label being applied on the inner surface of the cover to "20A".



4. Correcting the Operation and Maintenance Manual

Correct the fuse capacity for the fuse No. 23 of the Fuse Box III in Paragraph "Fuse capacity and circuit name" in Section 12.7 "Fuse" in Chapter 12 "Explanations of each device" of the Operation and Maintenance Manual.

(Fig. 2 blow shows where to correct in the Operation and Maintenance Manual.)

