COMPONENT CODE 54

INSTALLATION MANUAL

 REF NO.
 BT00047

 DATE
 Nov. 20, 2000


 Page 1 of 3

SUBJECT: INTRODUCTION OF SALT DAMAGE/CORROSION RESISTANT STAINLESS PARTS FOR WA500-3

- **PURPOSE:** To introduce newly prepared stainless steel made parts (handrails and muffler stack) which are effective to prevent occurrence of salt damages and corrosions for use on WA500-3 wheel loaders
- APPLICATION: WA500-3 Wheel Loaders, Serial Nos. 50001 and up

FAILURE CODE: 540054

DESCRIPTION:



This Installation Manual will introduce newly prepared stanless steel made handrails and muffler stack which are effective to prevent occurrence of salt damages and corrosions for use on the WA500-3 wheel loaders.

When locally installing these stainless steel parts to a ready shipped machines, follow the installation procedures outlined in this document.

2. List of parts

Part No.	Part Narie	Q'ty	Remarks
01010-81225	Bolt	14	
(01435-01225)	(Bol.)	(14)	
01010-81235	Polt	4	
(01435-01230)	(Boit)	(4)	
01643-31232	Washer	18	
425-54-25210	Handrail	1	
(425-54-25112)	(Handrail)	(1)	
42, 54 25220	Handrail	1	
(45-54-25122)	(Handrail)	(1)	
425-54-25230	Handrail	1	
(125-54-25132)	(Handrail)	(1)	
425-54-25240	Handrail	1	
(425-54-25142)	(Handrail)	(1)	
425-02-21130	Muffler stack	1	
(425-02-21120)	(Muffler stack)	(1)	
01020-10616	Bolt	10	
(01220-40616)	(Bolt)	(10)	




3. Installation procedures

① Replace the current hand rails with the stainless steel hand rails.

(Precautions) · As for the mounting bolts, replace the flanged bolts with the newly prepared bolts.


- Parts in thick-lined blocks _____ are the newly prepared parts for this modification.
- \cdot Bolt tightening torque: 98 123 Nm (10.0 12.5 kgm)



② Replace the current muffler stack with the stainless steel muffler stack.

(Precautions) · As for the mounting bolts, replace the flanged bolts with the newly prepared bolts.

- Parts in thick-lined blocks _____ are the newly prepared parts for this modification.
- · Bolt tightening torque: 98 123 Nm (10.0 12.5 kgm)



- ③ Replace the front light cover mounting crews with the prepared new bolts. (For both of the front light covers on the LH and CH sides)
- (Note) · Bolt tightening torque: $\frac{12.8}{12.8}$ · $\frac{14.7}{14.7}$ Nm (1.2 1.5 kgm)

