4 places, \triangle

COMPONENT CODE 45

INSTALLATION MANUAL

REF NO.	BT98045A
DATE	Feb. 13, 2002
-	Page 1 of 3

This INSTALLATION MANUAL supersedes the previous issue No. BT98045 dated Dec. 28, 1998 which should be discarded.

- SUBJECT: INTRODUCTION OF IMPROVED AIR RESERVOIR ON HD325-5, HD325-6, HD405-6, HD255-5
- PURPOSE: To introduce strengthened air reservoir for use on HD325-5, HD325-6, HD405-6 and HD255-5 dump trucks
- APPLICATION: HD325-5 Dump Trucks, Serial Nos. 2001 thru 4293 HD325-6 Dump Trucks, Serial Nos. 5001 and up HD405-6 Dump Trucks, Serial Nos. 1001 and up
 A HD255-5 Dump Trucks, Serial Nos. 1001 and up

FAILURE CODE: 451AFF

DESCRIPTION:

1-1. Introduction

With dump trucks of the above models being use. for hauling and disposing of rock at work sites where blasted rock (of a meter or hove of a side) are loaded onto them without crushing, (especially when the vehicle o dy is not equipped with rubber liners,) loading impact is very high and cracks may o cur in the weld joints of the air-reservoir relay valve mounting bosses.

This Service News introduces estre, gthened air reservoir with reinforced weld portions of the bosses for use on the change trucks being used under these working conditions.

- Although this modification was already introduced in the Service News No. A BT98045, this Service News will introduce it once again since the applicable models
 - \have been increased.


1-2. Revised places.

4 places A	Feo	Added the applicable model and changed the issuance number.

2. List of parts

Part No.	Part Name	Q'ty	Remarks
566-35-6A670	Air reservoir	1	
(566-35-42670)	(Air reservoir)	(1)	

3. Contents of the strengthening modification with the air reservoir Reinforcing plates have been supplemented to strengthen the relay valve mounting bosses.



- 4. Installation procedures
 - 1) Replace the air reservoir 1 with the strengthened air-reservoir.
 - Remove the piping and equipment being connected or installed to the air reservoir and connect them or install them to the new strengthened air reservoir after installing it.

