

PARTS & SERVICE NEWS

REF NO. AA03154

DATE November 5, 2003

(C)

Page 1 of 2

SUBJECT: SERVICE PARTS REVISION FOR PC0700 BLEEDDOWN MANIFOLD

PURPOSE: Correct parts book error


APPLICATION: Komatsu Electric Drive Dump Trucks:
930E-2: A30156 - A30300
930E-3: A30304

FAILURE CODE: RX10Z9

DESCRIPTION:

The service parts shown in the parts catalog are incorrect. With the information provided below, please update the service part numbers for PC0700 bleeddown manifolds in all applicable Parts Books.

Service Parts for PC0700 Bleeddown Manifold			
Item Number	Part Number	Quantity	Description
1	PB5916	2	Valve, Check
2	XA0200	2	Valve, Check
3	VE3054	2	Valve, Check
4	VE3833	1	Valve, Relief
5	XA0201	1	Plug, Cavity
6	BF5207	1	Valve, Solenoid
7	VF3830	1	Valve, Check
8	BF5202	1	Valve, Relief
9	VS7009	1	Cartridge
10	BF5204	1	Valve, Pilot Operated
11	XA2379	1	Piston, Pilot
12	XA0202	1	Coil, 24V



71051

FIGURE 1. BLEEDDOWN MANIFOLD (PC0700)