

PARTS & SERVICE NEWS

REF NO.	AA98125
DATE	17 September, 1998

SUBJECT: Back-up Alarm

PURPOSE: Announce New Parts for Improved Back-up Alarm

APPLICATION: 330M (BFP-41) & HD785-3; All S/N's Prior to A10190 (BFP-42)

FAILURE CODE: DV2099

DESCRIPTION:

Introduction:

The original rear back-up alarm installed on the trucks identified above has been changed in production (A10190 BFP-42 and later).

The design for the new back-up alarm has been changed to provide a more durable component. The new back-up alarm can be installed on older trucks with only minor changes to the mounting bracket on the truck chassis and installing parts as listed below:

Previous Design		Description	Current Design	
Quantity	Part Number		Quantity	Part Number
1	427-06-11310	Back-up Alarm	1	736131C2
-	--	Bracket	1	EG7283 *
-	--	C/S 0.37" - 16 UNC X 4.5"	2	H9918
-	--	L/W, 0.37"	2	C0312
-	--	Nut 0.37" - 16 UNC	2	C1521

The new back-up alarm must be installed near the same location as the previous installation in order to use the existing wiring. Connectors, such as WA3581 (qty. 2) may be used for electrical connections.

*** NOTE:**

If the existing mounting bracket is serviceable, it may be drilled to allow the fit of the new 736131C2 alarm; then the EG7283 bracket will not be required.