# PARTS & SERVICE

REF NO.	AA99002	
DATE	Dec. 28, 1998	
	Page 1 of 2	

**SUBJECT:** IMPROVED BELL CRANK PIN

**PURPOSE:** To introduce an improved bell crank pin

WA800-1 Wheel Loaders, S/N 10001 and up

APPLICATION: WA800-2 Wheel Loaders, S/N 10001 and up

WA800-2LC Wheel Loaders, S/N 10001 and up WA800-3 Wheel Loaders, S/N 50001 thru 50005 WA900-1 Wheel Loaders, S/N 10001 and up

WA900-1LC Wheel Loaders, S/N A20001 hru A20019 WA900-3 Wheel Loaders, S/N 50001 thru 50003

FAILURE CODE: 772E99

#### **DESCRIPTION:**

1. Introduction


This Service News will introduce an improved and more a rable bell crank pin (featuring a new material) for use on WA800 and WA900 wheel loaders.

### 2. List of parts

Part No.	Part Name	Ų įy	Remarks
427-70-11965 (427-70-11964)	Pin (Pin)	1 (1)	

#### 3. Contents of the modification

The material of the bell crank center pin has been changed from S45C to SCM435H to increase the durability of the part.



## 4. Precautions when replacing the part

When replacing the bell crank center pin, always apply "LM-P" to the pin and the bushing before installing them, in order to prevent galling or early wear. For details, refer to the previously issued Service News No. A796202 "PRECAUTION ATTACHMENT ASSEMBLY AT SITE ON WA700, WA800, "A920".