

PARTS & SERVICE NEWS

REF NO. AA99080

DATE April 7, 1999

Page 1 of 1

SUBJECT: TO CORRECT PARTS BOOK**PURPOSE:** To clarify the parts book.**APPLICATION:** WA900-1L Wheel Loader with Serial Number A20001 and up.**FAILURE CODE:** K10099**DESCRIPTION:**

The Parts Book for the WA900-1L Wheel Loader (Form Number BEPB002400) erroneously shows two switch pumps with service part breakdowns. The correct switch pump for the WA900-1L is Part Number 708-25-03091 and is shown in Figures 6051 through 6062 in section 6 of the Parts Book.

Figures 6031 through 6034 show the switch pump for the WA800-2L C, Part Number 708-45-10204, and is not used in the WA900-1L application. Remove or mark these pages in the Parts Book accordingly.

<https://hespareparts.com/>