

PARTS & SERVICE NEWS

REF NO.	A955028A
DATE	July 17, 2000

Page 1 of 2

*This **PARTS AND SERVICE NEWS** supercedes A955028, dated August 23, 1995, which should be discarded.*

SUBJECT: REROUTE OF TORQUE CONVERTER COOLING LINE

PURPOSE: To prevent the line from collapsing

APPLICATION: 568 Wheel Loader Serial Number 7001 through 7012
WA600-1LC Wheel Loader Serial Number A50001 through A50028

FAILURE CODE: 036030

DESCRIPTION:

Introduction:

In the original routing of the torque converter cooling line, an "S" curve in the line can cause the hose to cave in, leading to a restriction in oil flow. The new routing eliminates the "S" curve and one hose clip from the assembly.

PARTS LIST

Item	Part Number	Description	Qty	Remarks
1	07102-21029	Hose	1	
2	281-01-13180	Hose Clip	2	
3	426-62-13550	Tube	1	Shown for reference only

- The old and new routing of the torque converter cooling line:

