# PARTS & SERVICE NEWS

REF NO. AA00020

DATE 25, Jan. 2000


Page 1 of 2

SUBJECT:	Introduction Of Improved Elbow (562-13-46911) For Torque Converter Oil Pressure Sensor on Rear Dump Trucks
PURPOSE:	To introduce an improved oil pressure sensor mounting elbow
APPLICATION:	530M Rear Dump Truck All Transmission Assemblies Prior to s/n 5046 (Part# 562-14-41002) All Torque Convertor Assemblies Prior to s/n 1452 (Part# 562-13 21002)
FAILURE CODE:	131738

## **DESCRIPTION:**


The mounting elbow (1, Figure 1) for the torque converter oil pressure consor being used on the 530M may break from its bolt joint section when excessive vibrations are applied. The material of the mounting elbow has been changed to increase the durability to prevent breaking.

Old Part Number	New Part Number	Qty.		Description
562-13-46910	562-13-46911	2	EI BOW	





## NOTE: WHILE REPLACING THE MOUNTING ELBOW, PRECAUTIONS MUST BE MADE NOT TO ALLOW DUST AND OTHER FOREIGN MATERIAL INTO THE HYDRAULIC CIRCUITS.



# PARTS & SERVICE NEWS

REF NO. AA00020

DATE 25, Jan. 2000


Page 1 of 2

SUBJECT:	Introduction Of Improved Elbow (562-13-46911) For Torque Converter Oil Pressure Sensor on Rear Dump Trucks
PURPOSE:	To introduce an improved oil pressure sensor mounting elbow
APPLICATION:	530M Rear Dump Truck All Transmission Assemblies Prior to s/n 5046 (Part# 562-14-41002) All Torque Convertor Assemblies Prior to s/n 1452 (Part# 562-13 21002)
FAILURE CODE:	131738

## **DESCRIPTION:**


The mounting elbow (1, Figure 1) for the torque converter oil pressure consor being used on the 530M may break from its bolt joint section when excessive vibrations are applied. The material of the mounting elbow has been changed to increase the durability to prevent breaking.

Old Part Number	New Part Number	Qty.		Description
562-13-46910	562-13-46911	2	EI BOW	





## NOTE: WHILE REPLACING THE MOUNTING ELBOW, PRECAUTIONS MUST BE MADE NOT TO ALLOW DUST AND OTHER FOREIGN MATERIAL INTO THE HYDRAULIC CIRCUITS.



# PARTS & SERVICE NEWS

REF NO. AA00020

DATE 25, Jan. 2000


Page 1 of 2

SUBJECT:	Introduction Of Improved Elbow (562-13-46911) For Torque Converter Oil Pressure Sensor on Rear Dump Trucks
PURPOSE:	To introduce an improved oil pressure sensor mounting elbow
APPLICATION:	530M Rear Dump Truck All Transmission Assemblies Prior to s/n 5046 (Part# 562-14-41002) All Torque Convertor Assemblies Prior to s/n 1452 (Part# 562-13 21002)
FAILURE CODE:	131738

## **DESCRIPTION:**


The mounting elbow (1, Figure 1) for the torque converter oil pressure consor being used on the 530M may break from its bolt joint section when excessive vibrations are applied. The material of the mounting elbow has been changed to increase the durability to prevent breaking.

Old Part Number	New Part Number	Qty.		Description
562-13-46910	562-13-46911	2	EI BOW	





## NOTE: WHILE REPLACING THE MOUNTING ELBOW, PRECAUTIONS MUST BE MADE NOT TO ALLOW DUST AND OTHER FOREIGN MATERIAL INTO THE HYDRAULIC CIRCUITS.



# PARTS & SERVICE NEWS

REF NO. AA00020

DATE 25, Jan. 2000


Page 1 of 2

SUBJECT:	Introduction Of Improved Elbow (562-13-46911) For Torque Converter Oil Pressure Sensor on Rear Dump Trucks
PURPOSE:	To introduce an improved oil pressure sensor mounting elbow
APPLICATION:	530M Rear Dump Truck All Transmission Assemblies Prior to s/n 5046 (Part# 562-14-41002) All Torque Convertor Assemblies Prior to s/n 1452 (Part# 562-13 21002)
FAILURE CODE:	131738

## **DESCRIPTION:**


The mounting elbow (1, Figure 1) for the torque converter oil pressure consor being used on the 530M may break from its bolt joint section when excessive vibrations are applied. The material of the mounting elbow has been changed to increase the durability to prevent breaking.

Old Part Number	New Part Number	Qty.		Description
562-13-46910	562-13-46911	2	EI BOW	





## NOTE: WHILE REPLACING THE MOUNTING ELBOW, PRECAUTIONS MUST BE MADE NOT TO ALLOW DUST AND OTHER FOREIGN MATERIAL INTO THE HYDRAULIC CIRCUITS.



# PARTS & SERVICE NEWS

REF NO. AA00020

DATE 25, Jan. 2000


Page 1 of 2

SUBJECT:	Introduction Of Improved Elbow (562-13-46911) For Torque Converter Oil Pressure Sensor on Rear Dump Trucks
PURPOSE:	To introduce an improved oil pressure sensor mounting elbow
APPLICATION:	530M Rear Dump Truck All Transmission Assemblies Prior to s/n 5046 (Part# 562-14-41002) All Torque Convertor Assemblies Prior to s/n 1452 (Part# 562-13 21002)
FAILURE CODE:	131738

## **DESCRIPTION:**

The mounting elbow (1, Figure 1) for the torque converter oil pressure consor being used on the 530M may break from its bolt joint section when excessive vibrations are applied. The material of the mounting elbow has been changed to increase the durability to prevent breaking.

Old Part Number	New Part Number	Qty.		Description
562-13-46910	562-13-46911	2	EI BOW	





## NOTE: WHILE REPLACING THE MOUNTING ELBOW, PRECAUTIONS MUST BE MADE NOT TO ALLOW DUST AND OTHER FOREIGN MATERIAL INTO THE HYDRAULIC CIRCUITS.

