

PARTS & SERVICE NEWS

REF NO.	AA00050
DATE	July 21, 2000

SUBJECT: IMPROVED COOLING HOSE ROUTING (CHAMFER ADDED TO HOOD,
NEW MOUNTING BRACKET FOR COOLING HOSE)

PURPOSE: To inform the field of Part number change

APPLICATION: WA450-3L Wheel Loader, S/N A30001 and up

FAILURE CODE: 030099


DESCRIPTION:

Reason for this change is to eliminate possible interference between radiator hose and hood components.

Part Number for the support hose has been changed to 421-03-A1320 (30)

<https://hespareparts.com/>

RADIATOR PIPING (COOLING)



L06AH113

RADIATOR PIPING (COOLING)

Item	Part Number	Description	Qty.	Ref.
1	421-03-11990	TANK, RESERVE	1	
2	421-03-11980	.HOSE	1	
3	206-03-43340	.CLIP	1	
4	423-03-11340	BRACKET	1	
5	01435-00820	BOLT	2	
6	421-03-22130	HOSE	1	
7	206-03-43340	CLIP	2	
8	08036-11214	CLIP	4	
9	01010-51016	BOLT	4	
10	01643-31032	WASHER	4	
11	08034-20834	BAND	7	
12	421-03-A1280	HOSE, INLET	1	
13	07281-00809	CLAMP	4	
14	421-03-22140	TUBE, OUTLET	1	
15	07000-02075	O-RING	1	
16	01435-01290	BOLT	2	
17	421-03-22520	HOSE, OUTLET	1	
18	07281-00909	CLAMP	4	
19	07270-21087	TUBE, OVER FLOW	1	
20	07281-00167	CLAMP	2	
21	08034-20536	BAND	3	
22	07261-22010	HOSE, DRAIN	1	
23	07281-00419	CLAMP	2	
24	421-01-11263	TUBE	1	
25	01435-01020	BOLT	2	
26	424-01-11110	PLUG	1	
27	04434-53211	CLIP	1	
28	01435-01016	BOLT	2	
29	415-03-11540	HOSE	2	
30	421-03-11590	ELBOW	1	
31	421-03-A1320	SUPPORT, HOSE	1	
32	01435-01016	BOLT	1	
33	01435-01016	BOLT	1	
34	04434-53211	CLAMP	2	
35	01435-01016	BOLT	2	
36	08036-91414	CLIP	1	