COMPONENT CODE	20
----------------	----

PARTS & SERVICE NEWS

REF NO. | AA00077

DATE May 31, 2000

Page 1 of 1

SUBJECT: REPLACE THE SPIDER ASSEMBLY OF THE UPPER DRIVE SHAFT

PURPOSE: Cross assembly with 4 grease fittings no longer manufactured

APPLICATION: WA500-1L Wheel Loader Serial Number A20854 and UP WA500-1LC Wheel Loader Serial Number A60001 through A61000 WA500-1LE Wheel Loader Serial Number A61001 through A70020.

FAILURE CODE: 201199

DESCRIPTION:

Introduction:

This PARTS AND SERVICE NEWS announces an update to the above parts Books. PARTS LIST

Item	Part Number	Description	ીર	Remarks
1	425-20-A1130	Spider Assembly		Replace with 424-20-12620

Instructions:

• See Figure 1 for diagram of Upper Drive Shaft Ascembly.




Figure 1

