

PARTS & SERVICE NEWS

REF NO. AA00178

DATE August 2, 2000

Page 1 of 1

SUBJECT: PILOT D-RING REPLACEMENT ON FUEL PUMPS

PURPOSE: To reduce leaks

APPLICATION: S4D102E-1 Engine All Serial Numbers
S6D102E-1 Engine All Serial Numbers
S6D114E-1 Engine All Serial Numbers

FAILURE CODE: A7B013

DESCRIPTION:

Introduction:

This PARTS AND SERVICE NEWS introduces a new D-ring for the fuel pumps in the above engines. This new D-ring reduces leaks by swelling when coated with oil.

PARTS LIST

Item	Part Number	Description	Qty	Remarks
1	6731-21-3250	D-ring (New)	1	
2	6742-01-4030	D-ring (Old)	1	Superseded by Item 1
3	6741-01-0960	D-ring (Old)	1	Superseded by Item 1

IMPORTANT: Oil the D-ring just prior to installation.

NOTE: The outside of the D-ring can be identified by a paint ring around the outer circumference.

