

PARTS & SERVICE NEWS

REF NO. AA01174

DATE August 23, 2001

(C)

Page 1 of 2

SUBJECT: JOYSTICK STEERING UPGRADE

PURPOSE: To improve the performance of the joystick steering option.

APPLICATION: WA500-3L Wheel Loader Serial Number A70001 through A70832

FAILURE CODE: 43A0Z9

DESCRIPTION:

Although the system performs as designed, some operators have stated that the joystick steering feels "jerky" and is difficult to use.

This Parts and Service News provides a list of part and the procedure for upgrading the joystick steering system.

PARTS:

INDEX	PART NO.	DESCRIPTION	Q'TY
1	7823-25-1002	I/C Controller	1
2	426-60-21100	valve Assembly	1

The parts listed above are identical in appearance to the parts they are replacing. However, internal modifications have been made to change the performance of each.

Replace the parts indicated in the illustration.

Refer to the Shop Manual for Removal and Installation Procedures as well as all safety precautions.

Rework Instructions

