COMPONENT CODE 47

PARTS & SERVICE NEWS

REF NO. | AA02032

DATE January 10, 2001

Page 1 of 3

SUBJECT:	830E FRAME REPAIR FOR CRACKING
PURPOSE:	To inform the field of repair kits and repair procedures for cracking at four separate areas on 830E frames.
APPLICATION:	AFE32-CG & Up, AFE50-A thru K, A30544 thru A30602
FAILURE CODE:	4711HA
DESCRIPTION:	Frame repair kits: MK4157, MK4159, MK4161, MK4163

Some 830E trucks in operation have experienced frame cracking in the following areas:

- \cdot upper horsecollar
- · lower horsecollar
- front knee of frame rail (bebing horsecollar)
- · forward of frame rail casting to rail connection

Clean the truck and closely inspect the frame. Check for creating on both sides of the frame in the areas noted above. Refer to Figure 1 for approximate location, on the frame.

TABLE 1	FN AME REPAIR KITS
Part Number of Ast	Kit Description
MK4157	Upper Horsecollar Rework
MK41.	Lower Horsecollar Rework
M. X4161	Frame Rail (Knee) Rework
MK4163	Frame Rail Casting Rework

If a crack is four. In the of the specified areas, choose the corresponding kit to repair the crack(s). Each kit contains a driving with specific instructions for repair. The contents of each kit are listed in Tables 2 - 5.

Follow the welding procedures outlined in *Parts and Service News*, *FIELD WELDING FOR ASSEMBLY OR REPAIR* (#AA00046B). For additional welding guidelines, refer to *Welding I* (*SEBF14001*) and *Welding II* (*SEBF15002*).






TABLE 2. UPPER HORSECOLLAR REWORK KIT (MK4157) Part Number Description			
Part Number	Description	Quantity	
EJ2360	Drawing, Upper Horsecollar Rework	1	
EJ2356	Plate, Upper Loop	1	
EJ2355	Plate, Upper Rear	2	
ED8824	Bracket, Hydra Zorb	2	
WA3565	Channel, Special	8	
EJ2555	Backer	2	
EJ2554	Backer	2	
EJ2556	Backer	4	
EJ2553	Plate, Gusset	2	
	· ·	- C	

TABLE 3. LC	WER HORSECOLLAR REWORK KIT	(MK4159)
Part Number	Description	Quantity
EJ2359	Drawing, Lower Horsecollar Rework	1
EJ2353	Plate, Lower Loop	1
EJ2354	Plate, Lower Rear	2

TABLE 4. FRAME RAIL (J.N.LE) REWORK KIT (MK4161)				
Part Number	Description	Quantity		
EJ2358	Dravir, Fryme Rail (Knee) Rework	1		
EF7482	Breker	4		
EF7484	Ducker	4		
EF7483	Backer	4		
EJ2357	Plate, Gusset	2		

EJ2357	Plate, Gusset	2
TABLE 5.	FRAME RAIL CASTING REWORK KIT Description	(MK4163) Quantity
EJ2361	Drawing, Frame Rail Casting Rework	1
EJ2362	Backer	2
EJ2363	Backer	4
EJ2364	Backer	2