

# PARTS & SERVICE NEWS

REF NO. AA02107

DATE April 15, 2002

Page 1 of 1

**SUBJECT:** AIR CONDITIONING COMPRESSOR BELT GUARDS

**PURPOSE:** Introduce to the field a newly improved compressor belt guard.

**APPLICATION:** Komatsu Mechanical Drive Dump Trucks:  
530M: AFP49-A thru Y, A30001 thru A30038;  
HD1500-5: A30039 thru A30067

**FAILURE CODE:** 874NHA

**DESCRIPTION:** New air conditioning compressor belt guard (EJ9607).

Some trucks in the field may experience cracking at the air conditioning compressor belt guard. A new improved belt guard (EJ9607) has been developed to replace previous belt guard (EH8750), and to prevent this problem from occurring.

Differences in the new belt guard include transitions in the center wrap sheet and an added gusset. Refer to Figure 1.

Truck units A30068 and above will be assembled with the new belt guard.




FIGURE 1. NEW BELT GUARD (EJ9607)