

# PARTS & SERVICE NEWS

REF NO.	AA03157A
DATE	August 06, 2004

(C)

Page 1 of 2

*This Parts & Service News supersedes the previous issuance, AA03157, dated October 30, 2003. AA03157 should be discarded.*

**SUBJECT:** BLADDER REPAIR KITS FOR HYDRAULIC ACCUMULATORS

**PURPOSE:** To introduce repair kits for bladder accumulators.

**APPLICATION:** Komatsu Electric Drive Dump Trucks:

730E: A30219 and Up;  
 830E: A30689 and Up;  
 930E-2: A30294, A30301 thru A30303;  
 930E-3: A30304 and Up;  
**and all units equipped with bladder accumulators**

**FAILURE CODE:** 6031Z9

**DESCRIPTION:** Bladder Repair Kit (AK4787), Bladder Repair Kit (AK5064), and Bladder Repair Kit (AK4789)

Three bladder repair kits have been released for servicing the hydraulic bladder accumulators on the specified trucks. Table 1 lists the truck model, accumulator part numbers, accumulator capacity, and the part number of the applicable repair kit.

Refer to Tables 2 thru 4 for a complete listing of the contents of each kit.

TABLE 1. BLADDER REPAIR KITS

Truck Model	Accumulator (With Gas Manifold)	Accumulator (Without Gas Manifold)	Bladder Capacity	Bladder Repair Kit
730E	PC1811	XA2702	12.5 gallon	AK5064
830E	PC1811	XA2702	12.5 gallon	AK5064
930E	PC1116		10 gallon	AK4787
	PC1339	PC1121	16.5 gallon	AK4789

**TABLE 2. BLADDER REPAIR KIT (AK4787)**

<b>Part Number</b>	<b>Part Description</b>	<b>Quantity</b>
XA1931	Assembly, Gas Valve	1
XA0071	O-Ring	1
XA0072	Ring, Back-Up	1
XA1981	Seal, Dyna	1
XA1961	Assembly, Bladder (not serviced separately)	1
XA0070	Washer, Back-Up	1

**TABLE 3. BLADDER REPAIR KIT (AK5054)**

<b>Part Number</b>	<b>Part Description</b>	<b>Quantity</b>
XA2703	Assembly, Bladder (not serviced separately)	1
XA0070	Washer, Back-Up	1
XA0071	O-Ring	1
XA0072	Ring, Back-Up	1

**TABLE 4. BLADDER REPAIR KIT (AK4789)**

<b>Part Number</b>	<b>Part Description</b>	<b>Quantity</b>
XA1959	Assembly, Bladder (not serviced separately)	1
XA0070	Washer, Back-Up	1
XA0071	O-Ring	1
XA0072	Ring, Back-Up	1