

PARTS & SERVICE NEWS

REF NO.	AA03181
DATE	December 09, 2003

SUBJECT: ADDING A PASSENGER SIDE SUNVISOR

PURPOSE: To introduce a kit for adding a sunvisor to the passenger side of the cab.

APPLICATION: Komatsu Mechanical Drive Dump Trucks:
 330M: 24120 thru 24605, A10190 thru A10223, A10225 thru A10227, A10231 - A10232;
 HD785-5LC: A10144, A10224, A10228 and Up

FAILURE CODE: 5553Z9

DESCRIPTION: Sunvisor Assembly Kit (XK0287)

330M and HD785 trucks come from the factory with only a driver's side sunvisor. If so desired, a passenger side sunvisor may be installed. A kit has been developed that includes the necessary parts needed to install the additional sunvisor. Refer to Table 1 for a complete listing of the contents of the kit.

NOTE: Installation of the kit does not require drilling. Remove the screws from the existing holes and install the parts identically to the driver's side sunvisor.




TABLE 1. SUNVISOR ASSEMBLY KIT (XK0287)

Part Number	Description	Quantity
01220-40306	Screw	2
01220-40512	Screw	2
01225-40520	Screw	2
01641-20305	Washer	2
01641-20508	Washer	2
561-54-62191	Sunvisor Assembly	1
561-54-62980	Plate	1
561-54-62990	Catch	1
561-54-64680	Plate	1
561-54-64900	Cab Accessory Assembly (Drawing)	1