

PARTS & SERVICE NEWS

REF NO. AA05002

DATE January 10, 2005

Page 1 of 1

SUBJECT: BRAKE PRESSURE CONVERTER ASSEMBLY

PURPOSE: To inform the field of options available when ordering pressure converters.

APPLICATION: Komatsu Mechanical Drive Dump Trucks:
330M: 24120-24605, A10190-A10223, A10225-A10227, A10231, A10232;
HD785-3: A3001 - A3043;
HD785-5LC: A10144, A10224, A10228 -A10270;

FAILURE CODE: DDP6Z9

DESCRIPTION:

Some HD785-5LC parts books contain pressure converter (PC1061). Pressure converter (PC1061) has been replaced by comments to order pressure converter kit (EJ5912).

Pressure converter (EJ5912) includes (one) pressure converter (PC1061) and (one) rework drawing (EJ7249). The drawing illustrates the rework of (PC1061) by rotating the main body 180 degrees relative to the air canister. For complete details, refer to rework drawing (EJ7249). This rotation was required on older trucks due to interference with the mounting bracket.

Trucks with serial numbers A10271 and Up have incorporated a new mounting bracket (EJ5915) that does not need to have pressure converter (PC1061) reworked.

Pressure converter kit (EJ5912) will be supplied for both old and new trucks. The rework is required only on older trucks.