

PARTS & SERVICE NEWS

REF NO.	AA98114
DATE	JULY 22, 1998

Page 1 of 2

SUBJECT: NEW ELBOWS, INDICATOR HOSE, & HOSE ROUTING

PURPOSE: To inform the field

APPLICATION: WA500-1LE Wheel Loader with S/N A61001 and UP


FAILURE CODE: AA0099

DESCRIPTION:

Introduction:

This Parts and Service News releases to the field the new elbows, indicator hose and new indicator hose routing for the above machine.

When servicing the WA500-1LE Wheel Loader, S/N A61001 and UP, refer to this Parts and Service News first.



1. Add an elbow, p/n 175 775H1, to the air cleaner restriction indicator.
2. Replace the elbow, p/n 105 408, on the air filter housing with a new elbow, p/n 182 866 H1.
3. Replace the air cleaner indicator hose, p/n 08671-50110, with a new hose, p/n 425-01-A2440.
4. Route the new air cleaner indicator hose, p/n 425-01-A2440, so that it lies parallel to the top of the pre-cleaner housing. Refer to the NEW illustration on Page 1.

<https://hespareparts.com/>
