

PARTS & SERVICE NEWS

Ref.no.	AH01006
Date.	30.08.2001

Subject: Lighting – Rear lights

Purpose: Mounting of a distance piece between rear frame and rear light bracket.

Application: WA75-3:

Serial no. HA950

857 858 859 860 861 862 863 864 866 867 869 872 873
 875 876 880 883 884 891 903 905 907 908 909 913 916
 917 918 919 920 921 922 923 924 925 926 927 928 929
 930 931 932 933 934 935 936 937 938 939 940 944 945
 947 948 949 956 957 958 959 960.

WA85-3:

Serial no. HA960 166 167 168

Failure Code: DU3081

Description: On the Wheel Loaders WA75-3 and WA85-3 with the serial nos. above mentioned a distance piece between rear frame and rear light bracket has not be mounted.

This is an offense against the road regulation and it is not allowed to use the machine in the public traffic.

Therefore the distance piece (1) with two new screws (2) and two new shims (3) has to be mounted immediately at the left and right rear light.

Spare Parts: The necessary spare parts will be sent to you from our Service FCC.

Pos.	Name	P/N	Qty.
1	Distance piece	42U-06-13A60	2
2	Screw	423-00-H1270	4
3	Shim	421-00-H0760	4

