# PARTS & SERVICE

REF NO.	AT03045	
DATE	Apr. 4, 2003	
	Page 1 of 2	

SUBJECT: IMPROVEMENT OF REAR TIRE MUDGUARD FENDER ON HD465-7,

HD605-7

**PURPOSE:** To introduce modification procedure to prevent occurrence of riding of the

mud guard rubber on the hydraulic oil tank and its resultant deformation

on HD465-7 and HD605-7 dump trucks

**APPLICATION:** HD465-7 Dump truck, Serial Nos. 7001 thru 7089

HD605-7 Dump truck, Serial Nos. 7001 thru 7040

**FAILURE CODE:** 54A0EA

### **DESCRIPTION:**

### 1. Introduction

On the HD465-7 and HD605-7 dump trucks in the field, the mud guard rubber for the rear tires may come up over the hydraulic oil tank when the dump body is lowered resulting in deformation of the mud guard rubber.

This Service News will introduce the modification procedure to prevent occurrence of the aforementioned riding of the mud guard rubler and resultant deformation thereof.

# 2. List of parts

Part No.	Part Nanc	Purpose of part	Q'ty	Remarks
569-99-82290 (569-74-61660) (569-74-61660) 01010-81236 01643-3 (23.3	Plate (Guard) (Guard)  Bolt  Washer	Replacement	2 (2) (2) 14 14	Additionally working parts


## 3. Details of the modification

• To prevent occurrence of the interference between the mud guard rubber and the hydraulic oil tank, an angle changing plate is to be added between the mud guard rubber mounting support and the body and the length of the mud guard rubber is to be changed.


- 3-1. Preparations before starting the modification work
  - (1) Park the vehicle on a flat place, apply the parking brake and turn "OFF" the main switch. After that, insert chocks under each tire.
  - (2) When carrying out this modification work the dump body raised, be sure to insert the safety pins.

## 3-2. Modification procedure

(1) Remove the supports A and B (569-74-61630 (LH) and 569-74-61640 (RH)). (Since removed bolts and washers are being reused, store them carefully.)



- (3) Install the plate ① (569-932290) to the body using the bolt ③ (01010-81230) and washer (4) (01643-31232). At that time, be careful not to make directional error.
- (4) Install the supports A and B which have been removed as per the above Section (1) to the plate  $\bigcirc$ .



## 3-3. Confirmation

· Raise and lower the dump body to confirm that the mud guard rubber will not interfere with the hydraulic oil tank.