

PARTS & SERVICE

REF NO.	AT03249			
DATE	Dec. 19, 2003			
(C)	Page 1 of 3			

SUBJECT: MODIFICATION OF EXHAUST CONNECTOR ON S(A)A6D140 ENGINE

WITH EXHAUST BRAKE

PURPOSE: To introduce modification procedure to repair cracks in the exhaust con-

nector of S(A)6D140 engines equipped with the exhaust brake

APPLICATION: HD325-6 Dump Trucks, Serial Nos.

HD325-6E Dump Trucks, Serial Nos.

HM350-1 Articulated Dump Trucks, Serial Nos.

HM400-1 Articulated Dump Trucks, Serial Nos.

LW500-1 Rough Terrain Cranes, Serial Nos.

HV3000-1 Dump Trucks, Serial Nos.

Refer to page 3.

FAILURE CODE: A1R0HA

DESCRIPTION:


1. Introduction

In case cracks occur in the exhaust connector conjecting the turbocharger and the exhaust brake) of the S(A)6D140 engines, make the modification being introduced in this Service News to repair the cracks.

2. List of parts

Part No.	Part Naine	Purpose of part	Q'ty	Remarks
6211-11-5340 (6218-11-5340) 6212-11-5940 (6212-11-5940) 6151-11-5751 (6151-11-5751)	Connector (Cymestor) Gasket (Gasket) Gasket (Gasket)	Replacement	1 (1) 1 (1) 2 (2)	Consumable parts

3. Details of the modification



4. Modification procedure Carry out the modification work according to the Shop manual. (Replace the gaskets with new parts.)

Table of the serial numbers of the machines to which the modification in this Service News should be carried out and has been carried out at plant

Serial numbers in the field: Start from the initial serial number Serial numbers modified at plant: Produced in November, 2003 and after

	A 1: 1.1	Applicable engine serial No.		Applicable machine serial No.		
No.	Applicable model	Engines in the field	Engines modified at plant	Machines in the field	Machines modi- fied at plant	
1	HD325-6	Up to #31004	Next shipment and after	Up to #5960	#5691 and after	
2	HD405-6	Up to #31004	Next shipment and after	Up to #1186	#1187 and after	
3	HD325-6E	Up to #11206	#112520 and after	Up to #6251	#C!52 and after	
4	HD405-6E	Up to #11206	#112520 and after	Up to #2113	#2114 and after	
5	HM350-1	Up to #112470	#112533 and after	Up to #105	#1060 and after	
6	HM400-1	Up to #112508	#112529 and after	Up to #1116	#1117 and after	
7	LW500-1	Up to #31075	Next shipment and after	Up to #11035	#11036 and after	
8	HV3000-1	Up to #30646	Next shipment and after	ປາ ເບ#1011	#1012 and after	