

PARTS & SERVICE NEWS

REF NO.	BT04116
DATE	Sept. 7, 2004

Page 1 of 1

SUBJECT: KOMATSU PART NUMBER FOR THE REAR AXLE SUB-ASS'Y AS THE SPARE PARTS FOR HD1500-5

PURPOSE: To inform field personnel

APPLICATION: 530M-1 Dump truck S/N A30001 thru A30030, 32628
530M-4 Dump truck S/N A30031 thru A30035
530M-5 Dump truck S/N A30036 thru A30038
HD1500-5 Dump truck S/N A30039 and up

FAILURE CODE: 2B30Z9

DESCRIPTION:

1. Introduction

This Service News will introduce new Komatsu part numbers corresponding to the previous KA part number in order to make spare parts of the rear axle for the HD1500-5 dump trucks available.

2. List of parts

Part No.	Part Name	Q'ty	Remarks
562-33-30110 (EG9514SERV)	Rear brake sub group		
562-22-30110 (EJ3915SERV)	Rear diff service		
562-22-30210 (EJ3918SERV)	R. gear sub assembly		
562-22-30220 (EJ3925SERV)	Carrier sub assembly		