New CTP Replacement Parts for Heavy Equipment

CTP BONNETS



CTP Bonnets

CTP Bonnets are developed with the highest quality materials to withstand even in the roughest environment. Not only are built to last but CTP Bonnets also keep your systems leak free which ultimately prolongs the life of your machine running in excellent conditions.

| Part No. | Application | Engine |
|----------|-------------|---------------------------|
| 5S7607 | OIL COOLER | 3306, 3304 |
| 6N0124 | OIL COOLER | 3306, 3304, 3306B |
| 6N0125 | OIL COOLER | 3306, 3304 |
| 6N1131 | OIL COOLER | 3306 |
| 7N3340 | OIL COOLER | 3306 |
| 7N3512 | OIL COOLER | 3306 |
| 8\$3653 | OIL COOLER | 3306 |
| 8S4304 | OIL COOLER | 3406B, 3306, 3406B, 3406C |
| 9L5910 | OIL COOLER | 3306, 3306B |

| Part No. | Application | Engine |
|----------|-------------|-----------------------------------|
| 1W9171 | FUEL PUMP | 3306 |
| 1082102 | FUEL PUMP | 3406B, 3406C |
| 4M0411 | FUEL PUMP | 3306, 3304, 1673, D336, D333 |
| 4N0209 | FUEL PUMP | 3304, 3306, 3208 |
| 4N2484 | FUEL PUMP | 3406, 3408, 3412, 3208, 3408B |
| 8N1417 | FUEL PUMP | 3208, 3304 |
| 8N2516 | FUEL PUMP | 3204, 3304, 3402, 3306, 3306B |
| 9L6893 | FUEL PUMP | 3406, 3408, 3408B, 3412, 3412B |

* Other part no. not included in the list are available. Please contact your sales representative if you have any questions.

Part Numbers are used for reference purposes only

Quality with Value Guaranteed[™]