

PARTS & SERVICE NEWS

REF NO.	AA01130
DATE	June 26, 2001

Page 1 of 2

SUBJECT: REPAIR TO IMPROVE WATERPROOF-ABILITY OF T/M CONTROLLER MOUNTING SECTION

PURPOSE: To introduce modification procedures to improve the water proofing capability of the tranmission controller mount section. (Canopy or cab-less, Canopy-less with automatic shift transmission)

APPLICATION: WA120-3MC Wheel Loader Serial Number A31004, A31005 and A31022
WA180-3PTC Wheel Loader Serial Number A88007
WA180-3MC Wheel Loader Serial Number A81005 thru A81009, A81012, A81013, A81028, A81029, A81039, A81040, A81048, A81049, A81062
WA180PT-3MC Wheel Loader Serial Number A85030, A85045 thru A85049, A85058, A85067, A85069, A85072, A85074, A85153 thru A85160, A85178, A85179, A85182, A85209 thru A85211, A85212, A85226, A85252, A85259

FAILURE CODE: DA00PQ

DESCRIPTION:

The WA120-3 and WA180-3 Wheel Loaders equipped with the open ROPS canopy and the auto-shift transmission have experienced controller failures due to water entering the controllers. This **Parts and Service News** introduces a countermeasure to prevent water intrusion of the transmission controller.

LIST OF PARTS:

Part No.	Part Name	Purpose of part	Q'ty	Remarks
417-54-A2160	Sheet-rubber	Additional	1	

