COMPONENT CODE EB

PARTS & SERVICE NEWS

REF NO. | AA02233

DATE October 17, 2002

Page 1 of 2

SUBJECT: VISOR KIT FOR DIMMING MOM DISPLAY BRIGHTNESS

PURPOSE: Introduce to the field a kit for additional dimming of MOM display brightness.

APPLICATION: Komatsu Mechanical Drive Dump Trucks: 530M: A30001 thru A30038, 32628; HD1500-5: A30039 & Up

FAILURE CODE: EB10Z9

DESCRIPTION: MOM Display Visor Kit (XK0159)

Truck operators that continue to have visual problems with the Message 64 Operator and Maintenance (MOM) display due to excessive brightness may wish to install MOM cispnay visor kit (XK0159). The kit includes a visor and the necessary hardware for mounting over the MOM display. Visor (4, Figure 1) is mounted with hinges (5) that allow the visor to swing in and out of position depending on specific lighting conditions. Table 1 contains a complete listing of kit contents. An installation drawing that includes hole locators and specifications is included in the kit.

NOTE: Trucks operating without a MOM display diminer switch may upgrade to the current arrangement to date. Refer to Parts & Service News Bulletin 'REPLACEMENT MOM (MESSAGE for OPERA-TOR and MAINTENANCE) DISPLAYS (7818 92 2003) and MOM WIRING REWORK KIT (XK0025). ALSO PMC UPGRADES", AA02064.

TABLE 1. MOM Display Visor Kit (XK0159)		
Part Number	Description	Quantity
EK2946	Drawing, MOM Display Visor Kit	1
EK2943	Visor	1
<u>Г.К.294</u> 0	Hinge Set	1
ММ0336	Pan Head Screw	10
EK2944	Sheet Spacer	4
VN9764	Flatwasher	10
MM0371	Nut	10



