		СОМРО	NENT CODE 63
PARTS & SERVICE NEWS		REF NO.	AA03129
		DATE	Oct. 10, 2003
		(C)	Page 1 of 1
SUBJECT:	IMPROVED PPC ACCUMULATOR.		
PURPOSE:	Introduce part number for improved PPC accumulator.		
APPLICATION:	WA500-3L Wheel Loader Serial Number A70001 thru A70832 WA500-3LK Wheel Loader Serial Number A71001 thru A71224 WA600-3L Wheel Loader Serial Number A52001 thru A52224 WA600-3LK Wheel Loader Serial Number A53001 thru A53051		
FAILURE CODE:	6347AH		
DESCRIPTION:	The life of the PPC accumulator may be shortened due to heat generated by nor- mal pressure fluctuations in the PPC circuit. The accumulator has been improved by adding .05 L (50 cc.'s) of oil to the gas charge ride. The added oil will dissi-		

Remark

As stated in the Operation & Maintenance Manual, the PF Coccumulator should be checked every 2000 hours for proper operation. Refer to the O & M manual for the proper checking procedure.

pate heat more efficiently, extending the life of the accumulator diaphragm.

-- NOTE --

The information in this **PARTS & SERVICE NEWS** does not authorize or imply any obligation on the part of Komatsu America Company to provide reimbursement for any expenses. Machines requiring part repair or part replacement during the machine warranty are covered under normal warranty. Out-of-warranty machines are the responsibility of the distributor/customer.

