

# PARTS & SERVICE NEWS

REF NO.	AT00304
DATE	Feb. 1, 2001

Page 1 of 2

**SUBJECT:** IMPROVED SEAL FOR A/C OUTSIDE AIR FILTER BOX ON WA1200-3

**PURPOSE:** To introduce modification procedures to improve the sealing capacity of the outside air filter box on WA1200-3 wheel loaders

**APPLICATION:** WA1200-3 Wheel Loaders, Serial Nos. 50001 thru 50007

**FAILURE CODE:** 551027

**DESCRIPTION:**

1. Introduction

Since it has been found out that the sealing capacity of the outside air filter box located behind the operator's cab on the WA1200-3 wheel loaders is insufficient and there is a fear of occurrence of entry of dust into the operator's cab and of early stage blinding of the evaporator for the air conditioner unit, implement the modification being introduced in this Service News to prevent occurrence of the aforesaid failures.

2. List of parts

Part No.	Part Name	Purpose of part	Q'ty	Remarks
42C-07-13480	Seal	Addition	1	

### 3. Modification procedures

Apply the prepared seal to the filter box.

